

OFFICE OF THE EXECUTIVE ENGINEER RURAL WORKS DIVISION, BALASORE

No. 5779 / dt- 15/05/23

To

The Principal  
KCA PUBLIC SCHOOL  
Junia, Gopalpur, Balasore

Sub:- Issue of safety certificate in favour of KCA Public School.

Ref:- Ltr. No. 369, dtd. 27.04.2023 of Asst. Executive Engineer, R.W.  
Sub-Division, Balasore.

Sir,

With reference to the letter and above cited subject, it is to state that the Asst. Executive Engineer, R.W., Sub- Division, Balasore has visited the site of above mentioned school which is situated in the village Junia over Plot 4, 5, 96, 387, 105 having Kisam Gharbari total area Ac2.55Dec. in the district of Balasore and the inspection report of Asst. Executive Engineer, R.W. Sub- Division, Balasore attached herewith.

As per observation of concerned A.E.E. and eye estimation the building is Four storeyed (G+3) with group pile foundation on report of the Principal of school. The root of the entire structure is RCC and walls are made with fly ash brick having wooden shutters, windows are done with aluminium framing having glass panel. The floors of the building are finished with different type tiles and also in good condition.

Hence on the basis of present structural condition there is no problem for functioning of educational institution in the said building.

This is for your information and necessary action.

Yours sincerely

  
Executive Engineer

R.W. Division, Balasore

Memo No. \_\_\_\_\_ / dt \_\_\_\_\_

Copy to the Asst. Executive Engineer, R.W. Sub- Division, Balasore for  
information and necessary action.

Executive Engineer  
R.W. Division, Balasore